

SERVICE BULLETIN

Number 20170822

Date 08/07/2016

Title: Replacing mullion in the Shamrock ASF1370

Models effected: Shamrock ASF1370.



ABN: 55 051 202 067

Head Office

Unit 1/35 Rimfire Drive
Hallam, VIC 3803

Phone: 03 8786 3570

Fax: 07 5462 8396

sales@austwiderentals.com

Reasons:

1. Original Mullion was not earthed correctly.

Items Required:

1. New Mullion with Earth Wires attached. Part no.17442.
2. Pop rivet with Earth Tab Part No 17443
3. Philips screw driver No.2
4. Cordless Drill.
5. Pop Rivet Gun

Method:

1. Remove old Mullion. Dis
2. Fit Light fitting and Shelf Strips to the new Mullion.
3. Place New mullion into position
4. Attach Pop Rivet with Earth Tab to the area behind the Top Panel.
5. Screw Top Panel Closed.

Note: Earth continuity requires the top panel to be closed and screwed in place.



Part No 17443. Pop Rivet with Earth Tabs



Position of Pop Rivet